

**Federal Aviation
Administration**

Transmittal Letter 08-12

May 02, 2008

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA,
LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME,
MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:
.....EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
04/28/08	MN	Benson	Benson Muni	8/5198		NDB RWY 14, AMDT 7

AIRAC Date: 28 APRIL 2008

FDC 8/5198 BBB FI/P BENSON MUNI, BENSON, MN. NDB RWY 14, AMDT
7 ... CHART ALTERNATE MINIMUMS NA. THIS IS NDB RWY 14, AMDT 7A.