

**Federal Aviation  
Administration**

**Transmittal Letter 23-09**

**March 3, 2023**

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53  
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure  
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA,  
LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME,  
MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:  
.....EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
4/20/2023	TX	Tyler	Tyler Pounds Rgnl	3/1707	1/6/2023	ILS OR LOC RWY 4, Orig

**AIRAC Date: 20 APRIL 2023**

FDC 3/1707 TYR IAP TYLER POUNDS RGNL, TYLER, TX. ILS OR LOC RWY 4, ORIG...  
CHART: TDZE 542. S-ILS 4 DA 742/HAT 200 ALL CATS, VIS 1/2 SM ALL CATS. S-LOC 4 MDA  
900/HAT 358 ALL CATS, VIS 1/2 SM CATS A/B, 5/8 SM CATS C/D. DELETE NOTE:  
INOPERATIVE TABLE DOES NOT APPLY TO S-ILS 4. CHANGE NOTE TO READ: FOR INOP  
ALS INCREASE S-LOC 4 CAT C/D VISIBILITY TO 1 SM. THIS IS ILS OR LOC RWY 4, ORIG-A.  
2301061341-PERM