

**Federal Aviation  
Administration**

**Transmittal Letter 08-11**

**April 18, 2008**

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53  
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure  
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA,  
LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME,  
MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:  
.....EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
4/18/2008	ND	NORTHWOOD	NORTHWOOD MUNI-VINCE FIELD	8/1646	4/8/2008	RNAV (GPS) RWY 26 ORIG

**AIRAC Date: 18 APRIL 2008**

FDC 8/1646 4V4 FI/P NORTHWOOD MUNI-VINCE FIELD, NORTHWOOD, ND. RNA V (GPS)  
RWY 26, ORIG ... S-26 MDA 1660/HA T 543 ALL CATS. CIRCLING MDA 1720/HAA 603 ALL  
CATS. DELETE NOTE: GPS OR RNP-0.3 REQUIRED. THIS IS RNAV (GPS) RWY 26, ORIG-A.