

PREPARED BY THE PRODUCT SUPPORT GROUP, AJV-34

| By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:EFFECTIVE UPON PUBLICATION | | | | | | |
|--|-------|---------|----------|---------------|----------|------------------------------|
| AIRAC DATE | STATE | CITY | AIRPORT | FDC NUMBER | FDC DATE | SUBJECT |
| 7-Mar-13 | WA | Hoquiam | Bowerman | 3/0876 | 01/11/13 | RNAV (GPS) RWY 24, Amdt 2 |

FDC **3/0876** HQM FI/P IAP BOWERMAN, HOQUIAM, WA. RNAV (GPS) RWY 24, AMDT 2... DELETE NOTE: PROCEDURE NA FOR ARRIVALS AT ULESS ON V27 NORTHEAST BOUND, SOUPY ON V204 EASTBOUND AND PUGIC ON V27 SOUTHEAST BOUND. CHART PLANVIEW NOTE: PROCEDURE NA FOR ARRIVALS AT ULESS ON V27 NORTHEAST BOUND, AT SOUPY ON V204 EASTBOUND AND AT PUGIC ON V27 SOUTHEAST BOUND. THIS IS RNAV (GPS) RWY 24, AMDT 2A.