

**Federal Aviation
Administration**

Transmittal Letter 17-21

August 25, 2017

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA,
LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME,
MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:
.....EFFECTIVE UPON PUBLICATION

| AIRAC DATE | STATE | CITY | AIRPORT | FDC NUMBER | FDC DATE | SUBJECT |
|---------------|-------|--------|---------------------|---------------|-------------|---------------------------|
| 12-Oct-17 | VA | Moneta | Smith Mountain Lake | 7/0439 | 8/10/17 | RNAV (GPS) RWY 23, Orig-B |

AIRAC Date: 12 OCTOBER 2017

FDC 7/0439 W91 IAP SMITH MOUNTAIN LAKE, Moneta, VA. RNAV (GPS) RWY 23,
ORIG-B... CHART PROFILE NOTE: VISUAL SEGMENT - OBSTACLES. DELETE
PROFILE NOTE: DESCENT ANGLE NA. THIS IS RNAV (GPS) RWY 23, ORIG-C.
1707131533-PERM