

**Federal Aviation
Administration**

Transmittal Letter 21-23

September 17, 2021

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:EFFECTIVE UPON PUBLICATION						
AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
11/4/2021	WY	Torrington	Torrington Muni	1/9404	8/6/2021	GPS RWY 10, Orig- D

AIRAC Date: 4 NOVEMBER 2021

FDC 1/9404 TOR IAP TORRINGTON MUNI, TORRINGTON, WY. GPS RWY 10, ORIG-D... CIRCLING CAT C MDA 4880/HAA 673, CAT D MDA 4920/HAA 713. VIS CAT C 2 SM, CAT D 2 1/4 SM. THIS IS GPS RWY 10, ORIG-E. 2108021251-PERM