

PREPARED BY THE PRODUCT SUPPORT GROUP, AJV-34

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:
EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
15-Dec-11	MO	Mexico	Mexico Memorial	1/6036	10/31/11	VOR/DME RWY 24, Amdt 2

FDC **1/6036** MYJ FI/P IAP MEXICO MEMORIAL, MEXICO, MO.
 VOR/DME RWY 24, AMDT 2... CHART NOTES: VISIBILITY REDUCTION
 BY HELICOPTERS NA. WHEN VGSI INOP, STRAIGHT-IN/CIRCLING
 RWY 24 PROCEDURE NA AT NIGHT. DELETE ALL REFERENCE TO
 VDP. DELETE NOTE: VDP NA WITH COLUMBIA RGNL ALTIMETER
 SETTING. CHANGE MAP TO READ: HLV 15.2 DME. THIS IS VOR/DME
 RWY 24, AMDT 2A.