

**Federal Aviation  
Administration**

**Transmittal Letter 22-19**

**July 22, 2022**

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53  
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure  
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA,  
LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME,  
MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:  
.....EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
9/8/2022	HI	Honolulu	Daniel K Inouye Intl	2/6152	6/28/2022	ILS Y RWY 4R, Amdt 2

**AIRAC Date: 9 SEPTEMBER 2022**

FDC 2/6152 HNL IAP DANIEL K INOUE INTL, HONOLULU, HI. ILS Y RWY 4R, AMDT 2... RAISE THE S-ILS  
4R(ASTERISK) FROM DA 209/HAT 200 TO DA 258/HAT 250. CHART: TDZE 8. THIS IS ILS Y RWY 4R, AMDT  
2A. 2204110229-PERM