

**Federal Aviation  
Administration**

**Transmittal Letter 21-11**

**April 2, 2021**

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53  
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure  
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA,  
LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME,  
MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:  
.....EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
5/20/2021	PR	Mayaguez	Eugenio Maria De Hostos	1/6848	3/30/2021	VOR RWY 9, Amdt 10A

**AIRAC Date: 20 MAY 2021**

FDC 1/6848 MAZ IAP EUGENIO MARIA DE HOSTOS, MAYAGUEZ, PR. VOR RWY 9, AMDT 10A... CIRCLING CAT C MDA 1460/HAA 1432. ALTERNATE MINIMUMS CAT A/B 1100-2, CAT C 1500-3, NA WHEN LOCAL WEATHER NOT AVAILABLE. THIS IS VOR RWY 9, AMDT 10B. 2103181340-PERM