

**Federal Aviation
Administration**

Transmittal Letter 21-21

August 20, 2021

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:EFFECTIVE UPON PUBLICATION						
AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
10/7/2021	WA	Hoquiam	Bowerman	1/2183	8/11/2021	VOR RWY 6, Amdt 15

AIRAC Date: 7 OCTOBER 2021

FDC 1/2183 HQM IAP BOWERMAN, HOQUIAM, WA. VOR RWY 6, AMDT 15... CIRCLING CAT C MDA 800/HAA 782, CAT D MDA 860/HAA 842, VIS CAT D 2 3/4; TEYKU FIX MINIMUMS: CIRCLING CAT C MDA 800/HAA 782, CAT D MDA 860/HAA 842; VIS CAT C 2 1/4, CAT D 2 3/4. ALTERNATE MINIMUMS: STANDARD EXCEPT CAT C 800-2 1/4, CAT D 900-2 3/4. THIS IS VOR RWY 6, AMDT 15A. 2108051540-PERM