

BEAUFORT**MICHAEL J SMITH FLD** (MRH)(KMRH) 1 N UTC-5(-4DT) N34°44.03' W76°39.62'CHARLOTTE
H-9C, L-35B
IAP

10 B TPA—See Remarks LRA NOTAM FILE MRH


RWY 08-26: H5003X100 (ASPH) D-60 MIRL**RWY 08:** REIL. PAPI(P2L)—GA 3.0° TCH 45'. Brush.**RWY 26:** REIL. PAPI(P2R)—GA 3.0° TCH 43'. Thld dspclcd 290'. Road. Rgt tfc.**RWY 03-21:** H4191X150 (ASPH) S-12.5 MIRL**RWY 03:** PAPI(P2L)—GA 4.0° TCH 44'. Thld dspclcd 863'. Road.**RWY 21:** PAPI(P2L)—GA 4.0° TCH 54'. Thld dspclcd 516'. Trees. Rgt tfc.**RWY 14-32:** H4001X100 (ASPH) S-12.5**RWY 14:** Brush.**RWY 32:** Thld dspclcd 490'. Trees.**SERVICE:** S4 **FUEL** 100LL, JET A1+ **OX** 3, 4 **LGT** ACTIVATE REIL Rwy 08 and Rwy 26; PAPI Rwy 03 and Rwy 21; MIRL Rwy 03-21 and Rwy 08-26—CTAF. PAPI Rwy 08 and Rwy 26 opr continuously.**AIRPORT REMARKS:** Attended 1300Z±-dusk. For svc after hrs call 252-728-2323. Deer and birds on and invof arpt and bird-dropped shells may cause FOD. NS ABTMT procedures in effect ctc arpt mgr 252-728-1928. Avoid overflts of Beaufort Waterfront and Beaufort National Register Historic District. TPA—single engine 1000' AGL; twin engine 1500' AGL. No line of sight between rwy ends. Rwy 08-26 markings faded to nonexistent.**AIRPORT MANAGER:** 252-728-1928**WEATHER DATA SOURCES:** ASOS 135.375 (252) 728-2055.**COMMUNICATIONS:** CTAF/UNICOM 122.8Ⓡ **CHERRY POINT APP/DEP CON** 124.1**CLNC DEL** 125.65**RADIO AIDS TO NAVIGATION:** NOTAM FILE ISO.**KINSTON (L) VORTAC** 109.6 ISO Chan 33 N35°22.26' W77°33.50' 136° 58.4 NM to fld. 106/5W.

VOR unusable:

221°-231° byd 30 NM blo 2,000'

Blo 5,000'

Byd 10NM

**BILLY MITCHELL** (See HATTERAS on page 282)**BLADENBORO** (3W6) 0 E UTC-5(-4DT) N34°32.57' W78°46.69'

CHARLOTTE

116 NOTAM FILE RDU

RWY 02-20: 2850X135 (TURF) 0.6% up N**RWY 02:** Trees.**RWY 20:** Trees.**AIRPORT REMARKS:** Unattended. Rwy 20 has 90' trees 100' from thld offset 30' rgt of cntrln and 90' trees 250' from thld offset 100' left of cntrln. 80' trees west edge of rwy thld to thld and 80' trees east edge of Rwy 02 from thld to 500'.**AIRPORT MANAGER:** (910) 876-2331**COMMUNICATIONS:** CTAF 122.9