

RANCHO MURIETA (RIU)(KRIU) 1 W UTC-8(-7DT) N38°29.21' W121°06.17'

SAN FRANCISCO

144 TPA-944(800) NOTAM FILE RIU

L-2F, 3A

RWY 04-22: H3798X75 (ASPH)

RWY 04: VASI(V2L)—GA 3.0° TCH 12'. Road. Rgt tfc.

RWY 22: VASI(V2L)—GA 3.0° TCH 12'. Tree.

SERVICE: S2 **FUEL** 100LL, JET A **LGT** Rwy 04 VASI OTS indef. Arpt lgts opr 1600-0100Z.

AIRPORT REMARKS: Attended 1600-0100Z. Deer on and invof rwy. +30' obstruction lit power poles parallel to Rwy 04-22. All ultralights must comply with FAR 103 and have an operating acft radio. All transient acft rprd to park in designated transient area. Rwy 22 noise abatement procedures in effect, ctc arpt manager 916-354-2940. Ldg fees apply. PSTN single \$25, PSTN twin \$40, Turbo prop \$75, Jet \$100.

AIRPORT MANAGER: 916-354-2940

COMMUNICATIONS: CTAF/UNICOM 122.8

RCO 122.2 (RANCHO MURIETA RADIO)

CLEARANCE DELIVERY PHONE: For CD ctc NorCal Apch at 916-361-6874.

RADIO AIDS TO NAVIGATION: NOTAM FILE SAC.

SACRAMENTO (H) VORTACW 115.2 SAC Chan 99 N38°26.62' W121°33.10' 066° 21.3 NM to fld. 3/17E.

RAND MOUNTAIN N35°20.32' W117°41.02'

LOS ANGELES

RCO 122.4 (RIVERSIDE RADIO)

L-7C

RAVENDALE (O39) 0 N UTC-8(-7DT) N40°48.22' W120°21.97'

KLAMATH FALLS

5306 TPA-6106(800) NOTAM FILE RNO

RWY 17-35: H2607X30 (ASPH)

RWY 35: Thld dspcd 394'. Pole.

AIRPORT REMARKS: Unattended. Unpaved areas extremely soft when wet.

AIRPORT MANAGER: 530-251-8299

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Oakland ARTCC at 510-745-3380.

RED BLUFF MUNI (RBL)(KRBL) 2 S UTC-8(-7DT) N40°09.02' W122°15.13'

KLAMATH FALLS

352 B TPA—See Remarks NOTAM FILE RBL

H-3B, L-2H

RWY 15-33: H5431X100 (ASPH) S-30, D-65, 2S-83 MIRL

IAP

RWY 15: REIL. PAPI(P2L)—GA 3.0° TCH 40'. Rgt tfc.

RWY 33: REIL. VASI(V4L)—GA 3.0° TCH 40'.

SERVICE: S4 **FUEL** 100LL, JET A **LGT** ACTIVATE MIRL Rwy 15-33,

PAPI Rwy 15 and VASI Rwy 33—CTAF.

AIRPORT REMARKS: Attended 1500Z-dusk. Automated credit card fuel system 24 hours. Ultralight activity on and invof arpt. TPA-1852 (1500) turbojet ops, 1352 (1000) others. Rwy 15 calm wind rwy. Twys have hwy type edge reflectors.

AIRPORT MANAGER: 530-527-2605

WEATHER DATA SOURCES: ASOS 120.775 (530) 528-8030. HIWAS 115.7 RBL.

COMMUNICATIONS: CTAF/UNICOM 123.0

RCO 122.4 (RANCHO MURIETA RADIO)

® OAKLAND CENTER APP/DEP CON 132.2

AIRSPACE: CLASS E.

RADIO AIDS TO NAVIGATION: NOTAM FILE RBL.

(H) **VORTACW** 115.7 RBL Chan 104 N40°05.93'

W122°14.18' 329° 3.2 NM to fld. 321/18E. HIWAS.

VOR portion unusable:

280°-300° blo 3,500'

