

FRANKENMUTH**WM 'TINY' ZEHNDER FLD** (66G) 2 SE UTC-5(-4DT) N43°18.86' W83°42.60'

DETROIT

639 NOTAM FILE LAN

RWY 09-27: 2500X100 (TURF) LIRL 0.3 up E**RWY 09:** Thld dspclcd 394'. Road.**RWY 27:** P-line.**SERVICE:** LGT Rwy 09-27 LIRL not for public use.**AIRPORT REMARKS:** Attended irregularly. Snow removal intermittent; verify condition call 989-728-3684. Rwy 09-27 soft in spring and after heavy rain. Rwy 09, 7' ditch 60' from thld. Rwy 27 has crops up to 25' tall, 0' dist, 85' L/R. Rwy 09-27 marked with 3' yellow cones including Rwy 09 dspclcd thld.**AIRPORT MANAGER:** 810-625-6901**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Great Lakes Apch at 269-459-3345, when Apch clsd ctc Cleveland ARTCC at 440-774-0224/0490.**FRANKFORD DOW MEM FLD** (FKS)(KFKS) 2 SE UTC-5(-4DT) N44°37.51' W86°12.05'

GREEN BAY

634 B NOTAM FILE FKS

L-31B

RWY 15-33: H4050X75 (ASPH) S-25 MIRL 0.7% up NW**RWY 15:** Thld dspclcd 1094'. Road.**RWY 33:** REIL. PAPI(P2R)—GA 3.0° TCH 35'. Thld dspclcd 111'.

Trees.

SERVICE: FUEL 100LL LGT ACTIVATE MIRL Rwy 15-33; REIL Rwy 33; PAPI Rwy 33—CTAF.**AIRPORT REMARKS:** Unattended. Attendant on call, 231-930-7174 (manager cell) or 231-651-0751 (assistant manager cell). Fuel self-service with major credit card. Radio controlled model acft opr west of rwy. Deer and birds on and invof arpt. Hang glider activity along Lake Michigan lakeshore. Ramp fee for commercial acft. Arpt bcn located on hill 1.25 miles northwest of arpt. Admin bldg access, depress 5-3-2-1.**AIRPORT MANAGER:** (231) 930-7174**WEATHER DATA SOURCES:** AWOS-3 118.325 (231) 352-7573. AWOS-3 wind unrelbl.**COMMUNICATIONS:** CTAF/UNICOM 123.05

® MINNEAPOLIS CENTER APP/DEP CON 132.9

CLEARANCE DELIVERY PHONE: For CD ctc Minneapolis ARTCC at 651-463-5588.**RADIO AIDS TO NAVIGATION:** NOTAM FILE MBL.**MANISTEE (L) VORW/DME** 111.4 MBL Chan 51 N44°16.24' W86°15.24' 011° 21.4 NM to fld. 620/5W.

VOR unusable:

Blw 4,000'

Byd 6 NM

DME unusable:

320°-070° byd 22 NM blo 3,000'

