

LEONARDTOWN**ST MARY'S CO RGNL** (2W6) 4 NE UTC-5(-4DT) N38°18.92' W76°33.01'

142 B NOTAM FILE DCA

RWY 11-29: H4150X75 (ASPH) S-12.5 MIRL 0.4% up W**RWY 11:** REIL. PAPI(P2L)—GA 3.0° TCH 37'. Trees.**RWY 29:** REIL. PAPI(P2L)—GA 3.0° TCH 32'. Trees.**SERVICE:** S4 **FUEL** 100LL, JET A **LGT** ACTIVATE MIRL Rwy 11-29, REIL Rws 11 and 29—CTAF.**AIRPORT REMARKS:** Attended 1300-2200Z†. Self serve 100LL avbl with credit card. Deer on and invof Rwy 11-29 SS-SR. Glider and ultralight activity on and invof arpt. Rwy 29 15' depression (downslope) 300' from thld 150' rgt, 125' left. When R-4007 in effect, acft operating VFR at arpt must remain within 1.5 NM of arpt, at or blw 1500 MSL, and above 700' AGL. All VFR flt ops conducted within R-4007 shall be at or blw 1000' MSL. IFR and VFR apchs within R-4077 will be coordinated wth Patuxent Apch on 121.0 or by phone 301-342-3740.**AIRPORT MANAGER:** (301) 475-4200**WEATHER DATA SOURCES:** AWOS-3 119.575 (301) 373-6514.**COMMUNICATIONS:** CTAF/UNICOM 123.0Ⓡ **PATUXENT APP/DEP CON** 121.0 (1200-0400Z† Mon-Sun. Other times by NOTAM) other time ctcⓇ **POTOMAC APP/DEP CON** 135.625**CLEARANCE DELIVERY PHONE:** For CD when NHK Apch is clsd ctc Potomac Apch at 866-640-4124.**RADIO AIDS TO NAVIGATION:** NOTAM FILE DCA.**PATUXENT (L) VORTACW** 117.6 PXT Chan 123 N38°17.27' W76°24.01' 293° 7.3 NM to fld. 18/10W.

VOR unusable:

023 byd 10 NM blo 2,500'

024°-174° byd 11 NM blo 2,500'

175°-239° byd 10 NM blo 5,000'

240°-347°

348°-022° byd 11 NM blo 2,500'

TACAN AZIMUTH unusable:


150°-155° byd 25 NM blo 2,500'

155°-237° byd 11 NM blo 2,500'

DME unusable:

150°-155° byd 25 NM blo 2,500'

155°-237° byd 11 NM blo 2,500'

WASHINGTON
L-29E, 34E, 36I, A
IAP**MARTIN STATE** (See BALTIMORE on page 88)**MARYLAND** (See INDIAN HEAD on page 100)**MASSEY AERODROME** (MD1) 2 E UTC-5(-4DT) N39°17.96' W75°47.96'

73 NOTAM FILE DCA

RWY 02-20: 3000X100 (TURF)**RWY 02:** Trees.**RWY 20:** Thld dspcld 120'. Trees.**AIRPORT REMARKS:** Attended 1500-2200Z†. Gliders, hang-gliders, powered parachutes, ultralight activity on and invof arpt. Rwy thlds and sides marked with white cones. Rwy 20 dspcld thld marked with 3 white cones on both sides.**AIRPORT MANAGER:** 410-928-5270**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Philadelphia Apch at 800-354-9884

WASHINGTON

MEXICO FARMS (See CUMBERLAND on page 93)**MONTGOMERY CO AIRPARK** (See GAITHERSBURG on page 98)