



DEPARTURE ROUTE DESCRIPTION

TAKEOFF ALL RUNWAYS: Fly assigned heading and altitude for RADAR vectors to MSP VOR/DME then on MSP R-208 to ORSKY INT/MSP 85 DME. Thence

. . . .on transition or assigned route. Expect clearance to filed altitude/flight level 10 (ten) minutes after departure.

FORT DODGE TRANSITION (ORSKY1.FOD): From over ORSKY INT on FOD R-356 to FOD VORTAC.

OMAHA TRANSITION (ORSKY1.OVR): From over ORSKY INT on MSP R-208 to ONTIJ INT, then on OVR R-015 to OVR VORTAC.

NC-1, 31 JAN 2019 to 28 FEB 2019

NC-1, 31 JAN 2019 to 28 FEB 2019