


# LAKES THREE DEPARTURE

NC-3, 07 NOV 2019 to 05 DEC 2019



NOTE: Chart not to scale.

## DEPARTURE ROUTE DESCRIPTION

**TAKEOFF ALL RUNWAYS:** Climb on assigned heading for RADAR vectors to appropriate route. Expect filed altitude 10 minutes after departure.

**COLUMBIA TRANSITION (LAKES3.COJ):** From over MCI VORTAC on MCI R-107 to ANX VORTAC, then on ANX R-088 and COU R-292 to COU VOR/DME.

**FRANC TRANSITION (LAKES3.FRANC):** From over MCI VORTAC on MCI R-107 to ANX VORTAC, then on ANX R-088 to FRANC FIX.

**SPINNER TRANSITION (LAKES3.SPI):** From over MCI VORTAC on MCI R-075 and SPI R-265 to TWAIN FIX, then on SPI R-265 to SPI VORTAC.

**TWAIN TRANSITION (LAKES3.TWAIN):** From over MCI VORTAC on MCI R-075 and SPI R-265 to TWAIN FIX.

NOTE: RADAR required.  
NOTE: DME required.

TAKEOFF MINIMUMS  
Rwys 11, 18, 29, 36: Standard.

NC-3, 07 NOV 2019 to 05 DEC 2019

# LAKES THREE DEPARTURE