


AIRPORT DIAGRAM

AL-330 (FAA)

PORTLAND INTL (PDX)
PORTLAND, OREGON

NW-1, 10 SEP 2020 to 08 OCT 2020



CAUTION: BE ALERT TO RUNWAY CROSSING CLEARANCES.
READBACK OF ALL RUNWAY HOLDING INSTRUCTIONS IS REQUIRED.

AIRPORT DIAGRAM

PORTLAND, OREGON
PORTLAND INTL (PDX)

NW-1, 10 SEP 2020 to 08 OCT 2020