

| | | | | | |
|---|------------------------|---|-----------------------------------|----------------------------------|--|
| LOC/DME I-FUN 108.9 Chan 26 | APP CRS 095° | Rwy Idg TDZE 1026 Apt Elev 1026 | 9R 11730 1019 | 9L 1019 1026 | ILS or LOC RWY 9R HARTSFIELD/JACKSON ATLANTA INTL (ATL) |
|---|------------------------|---|-----------------------------------|----------------------------------|--|

RADAR required for procedure entry, DME.

Simultaneous approach authorized.

Inop table does not apply to sidestep Rwy 9L.

Rwy 9R
ALSF-2

MISSED APPROACH: Climb to 4000 on heading 100° and AHN VOR/DME R-235 to CONNI/AHN 30.2 DME and hold.

| | | | | | |
|--|--|--|-----------------------------|--------------------------|------------------------------------|
| D-ATIS ARR 119.65 DEP 125.55 | ATLANTA APP CON 127.9 379.9 | ATLANTA TOWER 8L-26R 8R-26L 9L-27R 9R-27L 10-28 RWYS 119.1 125.325 123.85 119.3 119.5 254.4 | ALL RWYS 121.9 | GND CON 121.75 | ALL RWYS 121.65 254.4 |
|--|--|--|-----------------------------|--------------------------|------------------------------------|

