

LOC/DME I-YKM
110.1
Chan **38**

APP CRS
094°

Rwy Idg
TDZE
Apt Elev
N/A
N/A
1099

LOC/DME BC-B
YAKIMA AIR TRML/MCALLISTER FLD (YKM)

Simultaneous reception of I-YKM and YKM DME required.
Circling NA south of Rwy 9-27.
When local altimeter setting not received, procedure NA.

MISSED APPROACH: Climb to 4600 via YKM VORTAC
R-252 to YKM VORTAC and hold, continue climb-in-hold
to 4600.

ATIS 125.25	SPOKANE APP CON★ 123.8 263.15	YAKIMA TOWER★ 133.25 (CTAF) 0 257.8	GND CON 121.9	CLNC DEL 121.9	UNICOM 122.95
-----------------------	---	--	-------------------------	--------------------------	-------------------------

MSA YKM 25 NM

8000

5400

340°

160°

BACK COURSE

BABRE YKM 17

5800

Procedure Turn NA

WUDNO YKM 13.4

4700

ADXAC YKM 10.6

3900

GULSY YKM 6.3

2160

HABVA YKM 5.3

4600

YKM

4600

Procedure Turn NA

4700

094°

3900

5.94° TCH 50

2160

Disregard glide slope indications.

CATEGORY	A	B	C	D
CIRCLING	1760-1 661 (700-1)	1940-2½ 841 (900-2½)	2280-3 1181 (1200-3)	

ELEV 1099

D

094°

TWR 1159

7604 X 150

0.7% UP

0.5% UP

3835 X 150

AS

MIRL Rwy 4-22

HIRL Rwy 9-27

REIL Rws 4, 9, and 22

YAKIMA, WASHINGTON

Amtd 3A 18JUN20

YAKIMA AIR TRML/MCALLISTER FLD (YKM)

46°34'N-120°33'W

LOC/DME BC-B