

BUCKLEY SFB (KBKF)

MISSED APPROACH: Climbing right turn to 8200 and intercept BKF TACAN R-148 direct BEKEE and hold or as directed by ATC.

CLNC DEL
121.6 275.8

70
5904
6074
LASTE BKF 4 6236
MUSOE BKF 6.5 RADAR 6525
BEKEE (IF) BKF 13 6566
DERYL BKF 16 7048
KATTT (IAF) BKF 28 7621
HOLD 10,000 8200
HOLD 12,000 10,000
148°
328°
R-148

EMERG SAFE ALT 100 NM 16,500

ELEV 5663		TDZE 5663
-----------	--	-----------

BUCKLEY SFB (KBKF)

HI-TACAN RWY 32