

ILS or LOC RWY 34
PORTSMOUTH INTL AT PEASE (PSM)

MALSR

MISSED APPROACH: Climb to 1500 then climbing left turn on heading 290° to 3000 and ENE VOR/DME R-242 to RAYMY INT/CON VOR/DME 22.5 DME/RADAR and hold.

KENNEDY
117.1 ENE
Chan 118

LOCALIZER 110.1
I-PSM

PEASE
Chan 112
PSM (116.5)

CONCORD
112.9 CON
Chan 76

YOKNZ
PSM (6.3)
RADAR

LOCIZER 110.1
I-PSM

MISSED APCH FIX

RAYMY
CON 22.5
RADAR

Procedure NA for arrival on ENE VOR/DME airway radials 178 CW 271.

Procedure NA for arrival on CON VOR/DME airway radials 061 CW 172.

Use of CON R-130 and ENE R-203 may be necessary to locate IDEED intersection.

ELEV 100 D TDZE 84

A 209±

MSA PSM 25 NM
2900

HOLD
4600
3000

(IF/IAF)
IDEED INT
PSM 12.3
RADAR
CON 43.3
ENE 31.1

ELEV 100 TDZE 84

91°

209°

248°

TWR 230

237°

0.3% DOWN

1:322X 150

345° 4.9 NM from FAF

HIRL Rwy 16-34

FAF to MAP 4.9 NM

	Knots	60	90	120	150	180
Min:Sec	4:54	3:16	2:27	1:58	1:38	

NE-1, 10 JUL 2025 to 07 AUG 2025

NE-1, 10 JUL 2025 to 07 AUG 2025