

| | | | | |
|---------------------------|------------------------|---|---|---------------------------|
| LOC I-BAL 109.7 | APP CRS 105° | Rwy Ldg 9953 TDZE 143 Apt Elev 143 | BALTIMORE/ WASHINGTON INTL THURGOOD MARSHALL (BWI) | ILS RWY 10 (CAT II & III) |
|---------------------------|------------------------|---|---|---------------------------|

| | | |
|---|------------|---|
| RADAR required for procedure entry. DME or RADAR required. | ALSF-2 | MISSED APPROACH: Climb to 2500 on BAL VORTAC R-105 to HURTZ/BAL 12.3 DME/RADAR and hold. |
|---|------------|---|

| | | | | |
|------------------------------|--|---------------------------------------|-------------------------|---------------------------|
| D-ATIS 115.1 127.8 | POTOMAC APP CON 119.0 282.275 (020°-100°) 119.7 290.475 (131°-180°) 124.55 317.425 (101°-130°) 128.7 307.9 (181°-019°) | BALTIMORE TOWER 119.4 257.8 | GND CON 121.9 | CLNC DEL 118.05 |
|------------------------------|--|---------------------------------------|-------------------------|---------------------------|

