


25163

ILS RWY 27 (CAT II)
TALLAHASSEE INTL (TLH)

MISSED APPROACH: Climb to 2000 then climbing right turn to 4000 on heading 092° and on SZW VORTAC R-140 to GACED INT/SZW 12.4 DME and hold, continue climb-in-hold to 4000.



ATIS	TALLAHASSEE APP CON ★	TALLAHASSEE TOWER ★	GND CON	CLNC DEL	UNICOM
119.45 239.25	135.8 317.4	118.7(CTAF) 0 257.8	121.9 348.6	126.65 275.8	123.075



Procedure NA for arrivals at CODYS on V7-295 southeast bound.

2000
↑

4000
hdg
092°

SZW R-140

GACED INT

GACED INT
I-PLQ 6.8
SZW 12.4

One Minute Holding Pattern

1800

094° → 1500
← 274° 1800

GS 3.00°
TCH 59

1051°

IM

I-PLQ 1.5

0.2

5.2 NM

1.2

CATEGORY	A	B	C	D
S-ILS 27	RA 114/12 100 DA 158			

CATEGORY II ILS - SPECIAL AIRCREW & AIRCRAFT CERTIFICATION REQUIRED

TALLAHASSEE INTL (TLH)
ILS RWY 27 (CAT II)