


VORTAC FBC	APP CRS	Rwy Ldg	4126
108.2	233°	TDZE	850
Chan 19		Apt Elev	851

VOR RWY 23  
BLUFFTON (5G7)



Use Findlay altimeter setting; when not received, use Lima altimeter setting and increase all MDA 20 feet, increase S-23 Cat C 1/8 SM and Circling Cat C/D visibility 1/4 SM.

MISSED APPROACH: Climb to 2500 then right turn direct FBC VORTAC and hold.

FDY ASOS 132.85	TOLEDO APP CON 120.8 317.55	UNICOM 122.8 (CTAF) 0
--------------------	--------------------------------	--------------------------

