


ILS or LOC RWY 2  
SAN LUIS VALLEY RGNL/BERGMAN FLD (ALS)

**MISSED APPROACH:** Climb to 8700 then climbing right turn to 11000 direct ALS VORTAC and hold, continue climb in hold to 11000.

UNICOM  
122.8 (CTAF) **L**

Procedure NA for arrivals  
at WAPRE on V368 southwest bound.

