




LOC/DME I-CBP 109.1 Chan 28	APP CRS 101°	Rwy Idg 8000 TDZE 815 Apt Elev 815
---	------------------------	---

ILS or LOC RWY 10L
JOHN GLENN COLUMBUS INTL (CMH)

DME or RADAR required.			 MALSR	MISSED APPROACH: Climb to 1400 then climbing left turn to 3000 direct APE VORTAC and hold.		
<div><div> Simultaneous approach authorized.</div><div> For inop ALS, increase S-LOC 10L Cat C/D visibility to 1% SM. * RVR 1800 authorized with the use of FD or AP or HUD to DA.</div></div>						
D-ATIS	COLUMBUS APP CON	COLUMBUS TOWER	GND CON	CLNC DEL	CPDLC	
124.6	125.95 371.975	132.7 257.8	121.9 348.6	126.3		

