



DEPARTURE ROUTE DESCRIPTION

**TAKEOFF RWY 6:** Climbing left turn direct to cross BOLME at or above 5000 and at or below 6000, then track as depicted to NAGGS at and maintain 6000, thence...

**TAKEOFF RWY 18:** Climbing left turn direct COWDA, then track as depicted to cross NAGGS at and maintain 6000, thence...

**TAKEOFF RWY 24:** Climbing left turn direct COWDA, then track as depicted to cross NAGGS at and maintain 6000, thence...

**TAKEOFF RWY 36:** Climbing left turn direct ERUBE, then track as depicted to cross NAGGS at and maintain 6000, thence...

...as depicted on assigned transition. Expect further clearance from ATC.

**ALTERNATIVE:** Initial RADAR vector climb-out option to rejoin RNAV routing at BOLME at or above 5000. All runways: Fly runway heading, maintain 6000. Request RADAR vector departure option with CLNC DEL upon initial contact.

**POTTSTOWN TRANSITION (NAGGS2.PTW):**

**MODENA TRANSITION (NAGGS2.MXE):**

**STOEN TRANSITION (NAGGS2.STOEN):**