

APP CRS  
111°

Rwy Ldg  
TDZE  
Apt Elev

6213  
9  
9

RNAV (GPS) RWY 10R  
OAKLAND INTL (OAK)

▽

▲

DME/DME RNP-0.3 NA.  
Helicopter visibility reduction below ¾ SM not authorized.

MISSED APPROACH: Climbing left turn to 5200 direct HAYZE and hold, continue climb-in-hold to 5200.

D-ATIS 133.775	NORCAL APP CON 125.35 263.15	OAKLAND TOWER 118.3 291.65 (Rwys 10L/R-28L/R, 15-33) 127.2 256.9 (Rwy 12-30)	GND CON 121.9 (Rwys 10L/R-28L/R, 15-33) 121.75 (Rwy 12-30)	CLNC DEL 121.1	CPDLC
-------------------	---------------------------------	--	--	-------------------	-------

Procedure NA for arrivals at MICRA on V107-301 westbound.

Final approach course offset 13.17°.

COMMO

DATTS

ENCOL

ALOIN 2.7 NM to CAXIN

0.8 NM to CAXIN

CAXIN

5200

HAYZE

4000

3000

1800

1000

4.6 NM

5 NM

2.6 NM

1.9 NM

0.8

0.5

CATEGORY	A	B	C	D
LNAV MDA	480-1 471 (500-1)		480-1¾ 471 (500-1¾)	
CIRCLING	560-1 551 (600-1)		660-1¾ 651 (700-1¾)	1380-3 1371 (1400-3)

REIL Rwy 10R  
TDZ/CL Rwy 30  
MIRL Rwy 15-33  
HIRL Rwys 12-30, 10L-28R, 10R-28L

OAKLAND, CALIFORNIA

Amdt 2 18SEP14

37°43'N-122°13'W

OAKLAND INTL (OAK)

RNAV (GPS) RWY 10R