

LOC/DME I-DMP <u>111.7</u> Chan 54	APP CRS 234°	Rwy Ldg 10000 TDZE 409 Apt Elev 435
--	------------------------	--

ILS RWY 23R (CAT II & III)
RALEIGH-DURHAM INTL (RDU)

RNAV 1-DME/DME/IRU or GPS or RADAR required for procedure entry.


ALSF-2




MISSED APPROACH: Climb to 1000 then climbing right turn to 2200 on RDU VORTAC R-356 to DUHAM INT/RDU 11 DME and hold.

Simultaneous approach authorized.

D-ATIS 123.8	RALEIGH APP CON 127.675 307.9	RALEIGH TOWER 127.45 257.8	GND CON 121.9 348.6	CLNC DEL 120.1	CPDLC
-----------------	----------------------------------	-------------------------------	------------------------	-------------------	-------




ELEV	435	D	TDZE	409
------	-----	----------	------	-----



REIL Rwy 32
MIRL Rwy 14-32
HIRL Rwy 5R-23L and 5L-23R
TDZ/CL Rwy 23R, 23L and 5L

1000 ↑	2200 ↗	RDU	DUHAM	VGSI and ILS glidepath not coincident (VGSI Angle 3.00/TCH 69).
-----------	-----------	-----	-------	--



	1161'	5.5 NM	3 NM	2.7 NM	3.1 NM	
CATEGORY	A		B	C		D
S-ILS 23R	CAT II RA 105/12 100 DA 509					
S-ILS 23R	CAT III RVR 06					

CATEGORY II & III ILS - SPECIAL AIRCREW
& AIRCRAFT CERTIFICATION REQUIRED