


LOC I-FNT <b>109.9</b>	APP CRS <b>094°</b>	Rwy Idg <b>7201</b> TDZE <b>771</b> Apt Elev <b>782</b>
---------------------------	------------------------	---

ILS or LOC RWY 9  
BISHOP INTL (F'NT)

DME or RADAR required for procedure entry. DME or RADAR required.			<div>MALSR</div> <div></div>	MISSED APPROACH: Climb to 3000 on FNT VORTAC R-093 to HARRO/FNT VORTAC 10 DME/RADAR and hold.	
<div><div><div>▼</div><div>▲</div></div></div> <div>DME from FNT VORTAC. Simultaneous reception of I-FNT and FNT DME required. For inop ALS, increase S-LOC 9 Cat C/D visibility to 1 1/8 SM. **RVR 1800 authorized with use of FD or AP or HUD to DA.</div>					
ATIS 133.15	GREAT LAKES APP CON ★ 118.8 257.9	FLINT TOWER ★ 126.3 (CTAF) 257.9	GND CON 121.9	CLNC DEL 121.75	UNICOM 122.95

CAUTION: Brightly lighted parking lot 4000' east of approach end of Rwy 27 can easily be confused for Rwy 27.

