

ILS or LOC RWY 18R
HUNTSVILLE INTL-CARL T JONES FLD (HSV)

ALSF-2

MISSED APPROACH: Climb to 1300 then climbing right turn to 3000 on heading 270° and RQZ R-230 to JUVLO/RQZ 28.7 DME and hold.

MISSED APCH FIX

112.2 RQZ
R-230
Chan 59

050°
2300

JUVLO
RQZ [28.7]

HOLD 5000
3000

005°
1 min
185°
R-295

ROCKET
112.2 RQZ
Chan 59

(IF/IAF)
HAGUR INT
RQZ [8]
RADAR

MSA RQZ 25 NM

180°
360°

[3200] [3700]

LOCALIZER 109.3
I-HSV

1300
↑
hdg
270°
RQZ
R-230
JUVLO
△
FEKER INT
RADAR
HAGUR INT
RQZ (8)
RADAR
One Minute
Holding Pattern
005° → 5000
← 185° 3000
GS 3.00°
TCH 56
2.9 NM
2.8 NM
6.6 NM
1600
2500
2500

ELEV 629 D TDZE 629

185°

18L

12600 X 150

TWR

18R

10001 X 150

36L

36R

TDZ/CL Rwys 18R and 36L
HIRL Rwys 18L-36R and 18R-36L

FAF to MAP 5.7 NM

Knots	60	90	120	150	180
Min:Sec	5:42	3:48	2:51	2:17	1:54