

ILS or LOC RWY 8
CENTRAL WISCONSIN (CWA)

MISSED APPROACH: Climb to 3000
direct ASARE and hold.



One Minute Holding Pattern

GS 3.00° TCH 55

HENPA I-CWA 3000 [6.7] RADAR

WOKOS I-CWA 1860 [3.1]

I-CWA 1640 [2.4]

I-CWA 1474 [1.4]

3000

257°

077°

3.6 NM

0.7 NM

1 NM

3000

ASARE