

LOC I-PKX

108.3

APP CRS

356°

Rwy Idg

4097

TDZE

1086

Apt Elev

1096

LOC RWY 36

JOHNSON COUNTY EXEC (OJC)

NA

Helicopter visibility reduction below ¾ SM not authorized.
For inoperative MALSRs, increase S-36 Cats A and B
visibility ¼ mile.

MALSR

A5

MISSED APPROACH: Climb to 1700
then climbing right turn to 2700 direct
HERBB LOM and hold.

ATIS 119.35	KANSAS CITY APP CON 118.9 251.075	EXECUTIVE TOWER★ 126.0 (CTAF) 225.4	GND CON 121.6	UNICOM 122.95
----------------	--------------------------------------	--	------------------	------------------

MSA PK 25 NM

KANSAS CITY 113.25 MCI Chan 79 (Y)

LOCALIZER 108.3 I-PKX

LOM/IAF HERBB 420 PK

ALTERNATE MISSED APCH FIX

NAPOLEON ANX 115.15 Chan 98(Y)

BUTLER 115.9 BUM Chan 106

ADF REQUIRED

ELEV 1096 TDZE 1086

MIRL Rwy 18-36

TWR 1157

36

1.1% UP

1097 X 75

356°

FAF to MAP 5.3 NM

Knots	60	90	120	150	180
Min:Sec	5:18	3:32	2:39	2:07	1:46

Remain within 10 NM		PK LOM	1700	2700	PK
2700		176°	356°	2700	2.85° TCH 40
CATEGORY		A	B	C	D
S-36		1580-¾	494 (500-¾)	1580-1 494 (500-1)	NA
CIRCLING		1620-1	524 (600-1)	1620-1½ 524 (600-1½)	NA

Olathe, Kansas

Amndt 2 18SEP14

38°51'N-94°44'W

JOHNSON COUNTY EXEC (OJC)

LOC RWY 36