

| | | | | |
|--|------------------------|-----------------------------|--|---|
| VORTAC RQZ 112.2 Chan 59 | APP CRS 043° | Rwy Idg TDZE Apt Elev | N/A N/A 764 | VOR-B HUNTSVILLE EXEC TOM SHARP JR FLD (MDQ) |
|--|------------------------|-----------------------------|--|---|

| | |
|---|---|
| DME required. | MISSED APPROACH: Climbing left turn to 3000 direct RQZ VORTAC and hold. |
|  | |

| | | | |
|--------------------------|---|-----------------------|--|
| AWOS-3PT 120.0 | HUNTSVILLE APP CON★ 125.6 354.1 | GCO 121.725 | UNICOM 123.0 (CTAF) 0 |
|--------------------------|---|-----------------------|--|

