


VOR RWY 2
HALIFAX/NORTHAMPTON RGNL (IXA)

MISSED APPROACH: Climbing left turn to 2000 direct
TYJ VORTAC and hold.

UNICOM
123.075 (CTAF) L

DME REQUIRED

IAF
TAR RIVER
117.8 TYI 
Chn 125

NoPT for arrivals on
TYI VORTAC
airway radials R-082, R-096,
R-174, R-196 and R-269.

MSA TYI 25 NM

3300

HIRL Rwy 2-20 **L**
REIL Rwy 2 **L**

20
A5

014° 5 NM

2000	TYI	VGSI and descent angles not coincident (VGSI Angle 3.00/TCH 25).
------	-----	--

ROWNN TYI 14 JEREB TYI 9.9

One Minute Holding Pattern

CATEGORY	A	B	C	D
S-2	780-1	636 (700-1)	780-1 $\frac{3}{4}$	636 (700-1 $\frac{3}{4}$)
C CIRCLING	780-1	635 (700-1)	780-1 $\frac{3}{4}$ 635 (700-1 $\frac{3}{4}$)	860-2 $\frac{1}{4}$ 715 (800-2 $\frac{1}{4}$)

HALIFAX/NORTHAMPTON RGNL (IXA)

36°20'N-77°38'W

VOR RWY 2