

ILS RWY 22L (CAT II & III)
JOHN F. KENNEDY INTL (JFK)

MISSED APPROACH: Climb to 500 then climbing left turn to 3000 via JFK R-190 to CHANT INT/19 DME and hold.

CATEGORY II & III ILS - SPECIAL AIRCREW
& AIRCRAFT CERTIFICATION REQUIRED

NE-2, 06 FEB 2014 to 06 MAR 2014

NE-2. 06 FEB 2014 to 06 MAR 2014