


ILS RWY 22L (CAT III)
NEW YORK/JOHN F. KENNEDY INTL (JFK)

MISSED APPROACH: Climb to 500 then climbing left turn to 3000 via JFK R-190 to CHANT INT/19 DME and hold.

**CATEGORY III ILS - SPECIAL AIRCREW
& AIRCRAFT CERTIFICATION REQUIRED**



NE-2, 07 MAR 2013 to 04 APR 2013

NE-2. 07 MAR 2013 to 04 APR 2013