

Flight Procedure Tracking Form		Action: FLIGHT CHECK	Task Type: ESV	Date Open: 07/27/2017	Task #: 2014091930556401021	Request #: 20140919305564
Procedure: BOY VOR/DME ESV			Airport ID: KGEY	Airport: SOUTH BIG HORN COUNTY		Reimbursable #: NO
City: GREYBULL	ST: WY	GPS #:	Estimated Chart Date: 10/12/2017		FICO #:	
Fac ID: N/A		Fac. Type:			Specialist: LIAM DONAHUE	
Procedure Review						
	Rec'd	Rel'd	Full Name	Comments		
Lead:	04/07/2017	06/05/2017	DONALD LANIER	Digitally signed by		
QA:	06/05/2017	06/05/2017	DONALD LANIER	BEV L BORDY		
Liaison:	06/05/2017	06/05/2017	MARY MCDONALD	Jul 27, 2017		
Procedure Comments:			Remark Type: INFORMATION			
BOY VOR/DME ESV: (2) FLIGHT INSPECTION ONLY CONTACT DON LANIER: AJV, 5431 MANAGER, 405.954.8242						

FIPC BASIC FORM							
PROCEDURE: RNAV (GPS) RWY 8 1			AIRPORT NAME: SOUTH BIG HORN COUNTY		AIRPORT ID: KGEY	SPECIAL CONTROL NO: SG-06-069-17	
FAC ID: KGEY08.01		CITY: GREYBULL			ST: WY	ORIG CHART DATE: 10/12/2017	
DFL TYPE: PROC/S	THIRD PARTY: <input type="checkbox"/> YES	EST. TIME ON SITE: 0.4	REIMB. NUMBER:		PTS TASK ID: 2014091930556401001		
PREFLIGHT NOTES							
REVIEWER:					DATE:		
COMMENTS:					CHECK ONE:		
					<input type="checkbox"/> FLT CK REQ <input type="checkbox"/> NFCR <input type="checkbox"/> REJECT		
							YES
					CPV COMPLETE?		X
PROCEDURE RESULTS							
INSPECTION DATE: 07/21/2017		CREW #: VN075	N #: N58	INSTRUMENT PROCEDURE STATUS: <input type="checkbox"/> SAT <input checked="" type="checkbox"/> SAT W/CHANGES <input type="checkbox"/> UNSAT		ARINC CODING: <input type="checkbox"/> SAT <input checked="" type="checkbox"/> SAT/GOLD <input type="checkbox"/> UNSAT	
FLIGHT INSPECTOR SIGNATURE: joel f hawkley @ 07/24/2017 12:50			PRINTED NAME: HAWKLEY, JOEL FEWENS				NOTAM INITIATED? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO
FLIGHT INSPECTOR REMARKS: Complete Satisfactory with Changes. Boysen Reservoir (BOY) VOR/DME ESV 338/D63/110/175 was NOT completed. This ESV to establish the fix PECK on V187 should be assigned to a separate procedure. Flight Inspection of PAPI RWY 08 has not been completed.							
IN-FLIGHT OBSTACLE REPORT							
OBSTRUCTION ID #:	COORDINATES OR LOCATION:		GNSS ALTITUDE (MSL):		BAROMETRIC ALTITUDE (MSL):		HEIGHT ABOVE GROUND LEVEL:

ESV Details

Originating Office :	Airspace Docket Number :	Request Type : Establish				
Facility Data						
Chart Name : BOYSEN RESERVOIR	City : BOYSEN RESERVOIR	Ident : BOY		State : WY		
Type/Class : DMER	Frequency : M1212	Reference No.: 17066051				
Expanded Service Volume Data: (Requesting Officer)						
ESV ID	Radial 1	Radial 2	Distance	Minimum Altitude	Maximum Altitude	
FAA 704281-022	338	0	63	110	175	
Requirement: FIX PECKK ON V187						
Signature: donahue liam		Routing Symbol:			Date: 06/02/2017	
Expanded Service Volume Data: (FIFO)						
ESV ID	Radial 1	Radial 2	Distance	Minimum Altitude	Maximum Altitude	Action Type
FAA 704281-022	338	0				
Requirement/Remarks:						
Signature:		Routing Symbol:			Date:	

ESV Details

Originating Office :		Airspace Docket Number :		Request Type : Establish	
Facility Data					
Chart Name : BOYSEN RESERVOIR		City : BOYSEN RESERVOIR		Ident : BOY State : WY	
Type/Class : H-VOR		Frequency : M117.8		Reference No.: 17066050	
Expanded Service Volume Data: (Requesting Officer)					
ESV ID	Radial 1	Radial 2	Distance	Minimum Altitude	Maximum Altitude
FAA 711609-026	338	0	63	110	175
Requirement: FIX PECKK ON V187					
Signature: donahue liam		Routing Symbol:			Date: 06/02/2017
Expanded Service Volume Data: (FIFO)					
ESV ID	Radial 1	Radial 2	Distance	Minimum Altitude	Maximum Altitude
FAA 711609-026	338	0			
Requirement/Remarks:					
Signature:		Routing Symbol:			Date: