


Flight Procedure Tracking Form		Action: FLIGHT CHECK	Task Type: TEXTUAL DP	Date Open: 09/07/2018	Task #: 2018090731616702001	Request #: 20180907316167
Procedure: RUMFORD ME KME63 ORIG			Airport ID: KME63	Airport: RUMFORD COMMUNITY HOSPITAL		Reimbursable #: NO
City: RUMFORD	ST: ME	GPS #:	Estimated Chart Date: 02/28/2019		FICO #:	
Fac ID: N/A		Fac. Type:			Specialist: CHRISTINE BAYSE	
Procedure Review						
	Rec'd	Rel'd	Full Name	Comments		
Lead:	09/07/2018			 <i>Digitally signed by</i> WARDELL HENNING Mar 14, 2019		
QA:			Dion Lancia, 10/25/18, 10/31/18			
Liaison:						
Procedure Comments:			Remark Type: INFORMATION			
SPECIAL USE PROCEDURE ACTIVE AIRNAV DATA USED FOR ME63 AIRPORT DATED 9/13/18. CONTACT: PAT MULQUEEN 405-954-4073 OR WARDELL HENNING 405-436-1902						

FIPC BASIC FORM						
PROCEDURE: RUMFORD,ME,KME63,0			AIRPORT NAME: RUMFORD COMMUNITY HOSPITAL		AIRPORT ID: KME63	SPECIAL CONTROL NO: YG-11-159-18
FAC ID: KME63		CITY: RUMFORD			ST: ME	ORIG CHART DATE: 02/28/2019
DFL TYPE: PROC/I	THIRD PARTY: <input type="checkbox"/> YES	EST. TIME ON SITE: 0.5	REIMB. NUMBER: AC0581	PTS TASK ID: 2018090731616702001		
PREFLIGHT NOTES						
REVIEWER:					DATE:	
COMMENTS:					CHECK ONE: <input type="checkbox"/> FLT CK REQ <input type="checkbox"/> NFCR <input type="checkbox"/> REJECT <div style="display: flex; justify-content: space-between; border-top: 1px solid black; border-bottom: 1px solid black; width: 100%;"> YES NO </div> CPV COMPLETE?	
PROCEDURE RESULTS						
INSPECTION DATE: 02/12/2019	CREW #: VN364	N #: HELO	INSTRUMENT PROCEDURE STATUS: <input checked="" type="checkbox"/> SAT <input type="checkbox"/> SAT W/CHANGES <input type="checkbox"/> UNSAT		ARINC CODING: <input type="checkbox"/> SAT <input type="checkbox"/> SAT/GOLD <input type="checkbox"/> UNSAT	
FLIGHT INSPECTOR SIGNATURE: kevin riese @ 02/14/2019 12:45			PRINTED NAME: RIESE, KEVIN JOHN			NOTAM INITIATED? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO
FLIGHT INSPECTOR REMARKS: Rumford Community Hospital, Rumford ME, TEXTUAL DEPARTURE PROCEDURE completed satisfactory.						
IN-FLIGHT OBSTACLE REPORT						
OBSTRUCTION ID #:	COORDINATES OR LOCATION:	GNSS ALTITUDE (MSL):	BAROMETRIC ALTITUDE (MSL):	HEIGHT ABOVE GROUND LEVEL:		